Approved For Release 2004/10/20 ETA-RDP80B01676R001800020043-6	25X1
	25X1
	25X1

SUPPLEMENT 16

TO

JOINT EVALUATION OF SOVIET MISSILE THREAT IN CUBA

PREPARED BY

Guided Missile and Astronautics Intelligence Committee

Joint Atomic Energy Intelligence Committee

National Photographic Interpretation Center

0100 HOURS

6 NOVEMBER 1962

Approved For Release 2004/10/20-254-RDP80B01676R001800020043-6	2 5 8 % 1
Approved For Release 2004/10/20-769A-RDP80B01676R001800020043-6	25X1
 	

ADDENDUM *

Preliminary analysis of photography of the port of 25%	(1
Mariel reveals that one Soviet vessel has departed, a second is in the act	
of pulling away from the pier with three canvas-covered missile trans-	
porters on deck, and a third (still loading) has six such transporters on	
deck. Two more transporters are located on the dock. There is room on	
the deck of the latter ship to accommodate these two along with the six	
already loaded.	

Approved For Release 2004/10/26 P.E.ARDP80B01676R001800020043-6	25 <u>X</u> 1	
7.pp. 67 64 7 67 1 61 64 65 2 56 77 167 2 6 7		25X1

NOTICE

25X1 25X1

			25X1	
This report is based on anal	ysis of four U-2	photographic missions		
and four lo	w-level missions			
Available coverage included the ports				
of Mariel, La Isabela, Cardenas, L	a Coloma, Matanz	as, Punta Gerardo and		
Casilda. Photography from eight l	ow-level missions	s flown		
was not available at the time of thi				

SUMMARY

- 1. Missile transporters and launching equipment have now begun to appear at the ports of Mariel, Isabela, and Casilda. Approximately half the number of missile transporters and launchers previously identified at the MRBM sites and all six IRBM launch rings are now evident on docks at these ports. This accounts, however, for only a portion of the missile equipment evacuated from the former sites. (Table 1 and Figure 1)
- 2. At least one Soviet cargo ship with a capability for below-deck missile storage has left the USSR for Cuba and could arrive in about two weeks.
- 3. Photographic coverage of the known IRBM and MRBM sites confirms that they are being abandoned. Some trucks and tents remain at several sites but these are probably waiting for transport.
- 4. Examination of photography of port facilities has not indicated any unusual security or containers suggestive of nuclear warheads or nosecones. There is no activity apparent at the probable nuclear bunkers at Remedios, Guanajay, and Sagua La Grande No. 1.
- 5. There is no indication of abandoning the SA-2 sites in Cuba; of those covered, all were judged to be operational.

- 6. No further IL-28 BEAGLE jet bombers have been assembled at the San Julian Airfield, but IL-28 crates have now been observed at Holguin airfield in eastern Cuba. (Figure 1)
- 7. Examination of the airports at Holguin and San Julian has not revealed any indication of the presence of nuclear warheads.

Approved For Release 2004/10/20-: <u>CHA-RDP</u> 80B01676R0018 0 0020043-6	58% 1 25X1
DISCUSSION	
1. Site 3 Latest coverage: U-2 Mission Clouds and haze precludes a detailed observation of the four evacuated launch positions. At least 26 tents, 8 barracks buildings, and 15-20 vehicles remain in the support area.	25X1
2. Site 1	25X1
Evacuation of this launch site is continuing. Although cloud cover precludes a detailed analysis of the four evacuated launch positions, activity in the support area showed a 4-truck convoy moving into the area. There was no activity at the arched-roof building or other miscellaneous buildings. Approximately 54 vehicles (trucks and trailers) and 26 tents were noted. 3. Site 2 Latest coverage: U-2 Mission The two launch points at the southeast end of this site were visible on	25X1

The two launch points at the southeast end of this site were visible on the most recent high-altitude photographic coverage. Cloud cover precluded observation of the other two launch positions.

The launch positions appear deserted and three missile-ready tents have been removed. Pre-formed concrete arches used in the building of the probable nuclear warhead storage bunker remain in the same position noted previously. Approximately 25 tents, 5 storage sheds and 77 miscellaneous vehicles (trucks and/or trailers) were noted in the area.

	Approved For Release 2004/10√20 <u>" €IA-RD</u> P80B01676R001800020043-6	考 浆1 25X1
	Air Defense Missiles	
	4. High-altitude flights by U-2 aircraft	:5X1
25X1	2	25X1
25X1 25X1	6. The movement of equipment from the Guanajay IRBM area to the port of Mariel is reported in in igs. Convoys of loaded vehicles, some spattered with mud, were observed moving to Mariel and returning empty.	X1
•	7. Photography indicates the presence of BEAGLE2 (IL-28) bombers at two widely separated locations in Cuba. (Figure 1)	!5X1

Approved For Release 2004/10/20 : CIA-RDP80B01676R001800020043-6 TOP SECRET

a. San Julian Airfield. -- Some 28 BEAGLES in various states of assembly have been noted at this field in western Cuba in the recent past.

one completed BEAGLE, one completed MASCOT (UIL-28, trainer), seven partially-assembled BEAGLES, and 18 fuselage crates were observed. The 28th, probably operational, was apparently out of the area at the time of coverage.

b. Holguin Airfield. -- At this new military airfield in eastern Cuba, nine BEAGLE fuselage crates were observed Some 25X1 40 smaller crates were also present, many probably containing BEAGLE sub-assemblies.

Mariel Port (Table 1 and Figures 1, 2, 3, and 4)

25X1

25X1

8. Four Soviet freighters are in port, including the Metallurg Anosov, Dvinogorsk and the Bratsk. One PT Boat is tied to pier and 8 KOMAR-class (PGMG) are moored north of the runway. Equipment inside a secured area includes -- 17 missile erectors (12 with stands), 4 missile stands, and 4 canvas-covered vehicles. One of the freighters has 7 trucks on the fantail, including a tank truck and three track-mounted cranes. Equipment at Mariel Pier includes -- 4 canvas-covered missile transporters, one erector, 11 prime movers, 11 fuel trucks, one generator/air compressor in hold of ship, 13 utility trucks, 28 truck vans (4 of which are in the ship), 49 trucks (4 of which are on the ship), 9 unidentified vehicles on the ship, 8 cargo vans on ship, 23 oxidizer trailers (one of which is on ship), 2 cherry pickers (one in ship hold), about 25 concrete arches, and 6 steel rings (one on deck, one definitely, 2 probably and 2 possible in hold of ship).

. 25X1	Punta Gerardo Secure Port Facility (Figure 1)
25X1	9. Construction continues on 3 buildings/sheds reported under construction There has been no other apparent change to 25X1 the permanent facilities. Three tents are now located at the entrance to the secured area. No change is apparent in the parked convey reports.
25X1	secured area. No change is apparent in the parked convoy reported The area now contains 26 cylindrical storage tanks (ap-
25X1	proximately 6 smaller tanks, 7 oxidizer trailers and 9 trucks.
25X1	Casilda Port (Table 1 and Figures 1 and 5)
25X1	10. On
	La Isabela Port (Table 1 and Figure 1)
25X1	
	11. Two Soviet freighters, the Alapayevsk and a sister ship, are in port. Equipment at the pier area includes one cherry picker, 4 caterpillars,

10 generators/compressors, 59 trucks, 2 semi-trailers, 7 AT-T prime movers, 15 AT-S prime movers, 4 mobile cranes, and 2 graders. Seven

trucks (2 with trailers) are leaving the pier area.


Approved For Release 2004/10/20 : CIA-RDP80B01676R001800020043-

2**多**茶1 25X1

	Matanzas Port (Figure 1)
25X1	
	12. Vessels in the area include Patrol frigate Caribe No. 457, one unidentified patrol craft, lighthouse tender Enrique Collazo No. H-1, and the merchant vessel, Amata (USSR). Fourteen trucks and 2 small trailers are on dock. No apparent change in facilities since last observed
25X1	is to be noted.
25X1	Cardenas Port (Figure 1)
	13. Two coastal tankers and various small craft are in the area. No change in facilities since last observed
25X1	La Coloma Port Facilities (Figure 1)
25X1	14. Numerous small craft are in the port area. No apparent change in facilities since is to be noted.

TABLE 1
SOVIET OFFENSIVE MISSILE EQUIPMENT

G : 4 Minaila	Total Authorized	Max Total	C	bserved in Port	s	
Soviet Missile Equipment	Equipment (Est)	Observed	Mariel	La Isabella	Casilda	_
MRBM						
Missile Transporters	48	33	4	0	12	25X
Erectors	24	24	18	0	4	
Launch Stands	24	24	16	0	4	
Fuel Trailers	48	31	11	0	16	
Oxidizer Trailers	96	71	23	0	2	
Van Type Trucks	UNK	23	56	0	-	
Generators	UNK	13	1	10	-	
IRBM						
Propellant Trailers	UNK	4	4	Ü.		



Approved For Release 2004/10/20 : CIA-RPP80B01676R001800020043-6 TOP SECRET

25X1 25X1

25X1





